

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/09/2023

Document Number:

710500050

FIELD INSPECTION FORMLoc ID 384662 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Neher, Morgan		morgan@chemco-og.com	
Sanchez, Chris		chris.sanchez@state.co.us	
Neher, Gray	303-771-7777/9006	bogray@msn.com	

General Comment:

This is an Environmental Inspection for the Donohoe 4-A, Location ID 384662 active well location and Tank Battery, located in Kiowa County, Co

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: Yes

Comment: Oil Stains observed within Secondary Containment for Tank Battery, Maintain Equipment per Rule 608.e and cleanup impacted soils

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: Fencing around Pumping Unit needs Inadequate

Corrective Action: Repair and maintain fencing per Rule 608.e

Date: 11/08/2023

Equipment:

corrective date

Type: Pump Jack

1

Comment: Oil Stains Observed at well head

Corrective Action: Cleanup affected soil and maintain equipment within compliance of rule 608.e

Date: 11/08/2023

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2		STEEL AST		,

Comment: Tank Placards illegible

Corrective Action: Comply with Rule 605.h. for Tank and Container labels.

Date: 12/13/2023

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate

Comment: Tank Battery Berms appear to be inadequate, Operator shall calculate volume to assure compliance with Rule 603.o.

Corrective Action: Comply with, Rule 603.o.

Date: 11/21/2023

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

COGCC Comments

Comment	User	Date
Replace Placard labels for Tank Battery, Cleanup stained soil within Secondary Containment.	sanchezcc	10/09/2023
Inspect and measure Tank Battery Secondary containment to assure compliance with Rule 603. o.	sanchezcc	10/09/2023
Install/repair fencing around pumping unit.	sanchezcc	10/09/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403554762	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278447
710500051	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278429