

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2023

Submitted Date:

10/16/2023

Document Number:

709700196

### FIELD INSPECTION FORM

Loc ID 320324 Inspector Name: Huck, Keith On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 76859Name of Operator: SCHREIDER & COMPANY INCAddress: 9227 E LINCOLN AVE SUITE 200City: LONE TREE State: CO Zip: 80124**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments3 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203451	WELL	SI	07/01/2018	OW	001-09010	COMANCHE CREEK 1-14	SI

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	Access road grown over		
Corrective Action:		Date:	

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	_____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds throughout location		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence knocked down by cattle		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,

Comment:						Date:	
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate			
Comment:		Berms in disrepair					
Corrective Action:		Repair or install berms or other secondary containment devices per Rule 603.o.				Date:	11/30/2023
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	OTHER	STEEL AST				
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity) 210bbbls							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate			
Comment:		Berms in disrepair					
Corrective Action:		Repair or install berms or other secondary containment devices per Rule 603.o.				Date:	10/30/2023
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	300 BBLs	STEEL AST		39.880309,-104.294089		
Comment:							
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate			
Comment:		Berms in disrepair					

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.	Date:	12/01/2023
--------------------	--	-------	------------

**Wells Served By Facilities Above**

**AirsID**

API Number
001-09010

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 203451 Type: WELL API Number: 001-09010 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Routine (OWP) Inspection</a>	huckk	10/16/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709700197	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6285481">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6285481</a>
709700198	Flowline Measurement	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6285482">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6285482</a>