

# Inspection Photos

Loc: 324507

Operator: **OXY USA INC**

Inspection Date: 10/11/2023

County: Huerfano



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast along the access road ascending the hill to the location. There has been recent work performed along the west side of the road.





## Inspection Photos



**Photo 2.** Facing southeast along the east side of the road. Grading has pushed out material into a berm which is not allowing stormwater to be diverted off the road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:324507 | Date: 10/11/2023



## Inspection Photos



**Photo 3.** Facing northwest back down the access road. Grading has pushed out material into a berm which is not allowing stormwater to be diverted off the road. There is a long stretch of the road where stormwater will be directed down the road which will cause erosion.





## Inspection Photos



**Photo 4.** Facing southeast along the east side of the road. Some of the rock check dams installed have filled in with sediment and need maintenance. There was erosion observed underneath some of the rocks which were not properly constructed.





## Inspection Photos



**Photo 5.** Facing northwest at the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:324507 | Date: 10/11/2023



## Inspection Photos



**Photo 6.** There is a white powder substance spill on the ground that needs to be cleaned up. Previous corrective action was not completed.





## Inspection Photos



**Photo 7.** There is still cement debris that has not been removed.





## Inspection Photos



**Photo 8.** Facing back southeast at the location. There is a bent electric utility at this site that needs to be removed.

