

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2023

Submitted Date:

10/17/2023

Document Number:

712700752**FIELD INSPECTION FORM**Loc ID 325962 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:24 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|------------------------------------|
| , General | | sjninspections@ikavenergy.com | All SW Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 215640 | WELL | PR | 04/01/1989 | CBM | 067-07245 | ALBRIGHT-TRIMBLE 1 | PR |

General Comment:[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Electric code gate, private road. | | |
| Corrective Action | L | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | NFPA placards on separator and meterhouse. | | |
| Corrective Action: | | | Date: |
| Type | CONTAINERS | | |
| Comment: | Contents labeling on container. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Metal sign posted at fenced equipment enclosure. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 24 hour operator contact number and 911 local emergency number posted on well location signage. | | |
| Corrective Action: | | | Date: |
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Observed impacted material on ground at the wellhead assembly. See Photo #4. | | |
| Corrective Action: | Conduct maintenance on equipment, cleanup stained material and increase self inspection intervals. | | Date: 10/31/2023 |
| Type | WEEDS | | |
| Comment: | Tall vegetation growing up against fenced equipment enclosure. | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: <input type="text"/> | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Cattle panel around telemetry, separator, and meterhouse. | | |
| Corrective Action: | | | Date: |
| Type | OTHER | | |
| Comment: | Pipe rail around cathodic protection. | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|---|-------|--|
| Type | PUMP JACK | | |
| Comment: | Metal mesh around pumpjack. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Cattle panel around wellhead and pumpjack. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Cattle panel around electrical service and transformer boxes. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Chemical additive container. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | On separator vent stack. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | 2" line from separator to meterhouse. Calibration date 8/9/2023. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Telemetry, electrical service panel, electrical transformer. | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | PVC access | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | 3" line from wellhead to separator. | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-------------------------|----------------------------|------------------------|-------------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 215640 | Type: | WELL | API Number: | 067-07245 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 06/28/2023 | Annual Brhd Completed? | Yes | | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 0 | Fluid Type: | | | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Berms | Pass | Culverts | Pass | Material Handling And Spill Prevention | Pass | Container within containmnet. |
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Ditches | Pass | | | |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 712700759 | Well Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286548 |