

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2023

Submitted Date:

10/17/2023

Document Number:

713600302**FIELD INSPECTION FORM**Loc ID 324498 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 66561Name of Operator: OXY USA INCAddress: PO BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
OXY		COGCCinspections@oxy.com	
NEWVILLE TONI		toni_newville@oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324498	LOCATION	AC			-	DIKE MOUNTAIN UNIT- 628S70W 13SENW	RI

General Comment:

On 10/11/2023, Ryan Costa conducted a follow up of the previous inspection #690204292.
Operator is directed to perform corrective actions outlined on this inspection report immediately.
See attached photos and additional details within this report.

Location

Lease Road:			
Type	Access		
comment:	The access road is not maintained to allow safe vehicle access to the wellsite. There are areas of the road that are very steep with trees and large rocks fallen down along the road. Access roads must be maintained in in a stable condition to accommodate all weather access. Corrective action will remain out of compliance until completed.		
Corrective Action	Comply with Rule 603.I.	Date:	10/11/2023

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There has been grading of the access road performed since previous inspection but no other BMP's were installed. Grading activities as the only BMP is not sufficient to stabilize the road. BMP's along the steep road must be selected based off of site specific conditions and must be implemented in accordance with good engineering practice. Corrective action will remain out of compliance until completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600303	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6286552