

Interim Reclamation and Stormwater Inspection

October 11, 2023

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 439459

Inspection Document #: 697504908

Weld County, CO

SESE Section 28 T12N R65W

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Motu East /2821-8CH
Location ID: 439459



Photo 1. Photo taken from the entrance of location.
Photo illustrates Operator signage.



Photo 2. Photo taken from the southeastern location.
Photo illustrates trash that needs to be removed and properly disposed of. Trash was observed throughout the location and continues to be issue.

Inspection Photos
Location Name: Motu East /2821-8CH
Location ID: 439459



Photo 3. Photo taken from the southern interim reclamation area, facing West. Photo illustrates additional reclamation was performed and some desirable vegetation was observed and is in process of establishing.



Photo 4. Photo taken from the southern interim reclamation area, facing East. See comments under Photo 3.

Inspection Photos
Location Name: Motu East /2821-8CH
Location ID: 439459



Photo 5. Photo taken from the wellhead. Photo illustrates stained soil around the wellhead and outside of the cattle guards.



Photo 6. Photo taken from the interim reclamation area, facing South. Photo illustrates improper waste disposal and waste management.

Inspection Photos
Location Name: Motu East /2821-8CH
Location ID: 439459



Photo 7. Photo taken of secondary containment which is missing wildlife protection (netting). Secondary containment is for coolant.



Photo 8. Photo taken from within the secondary containment. Stained soil/gravel needs to be removed, cleaned out and properly disposed of.

Inspection Photos
Location Name: Motu East /2821-8CH
Location ID: 439459



Photo 9. Photo taken from within the secondary containment. Stained soil/gravel needs to be removed, cleaned out and properly disposed of.



Photo 10. Photo taken along a portion of the access road, facing West. Photo illustrates rill erosion in need of repair.

Inspection Photos
Location Name: Motu East /2821-8CH
Location ID: 439459



Photo 11. Photo taken from the entrance of location off CR 136. Photo illustrates culvert has been repaired.