

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2023

Submitted Date:

10/13/2023

Document Number:

707800665

**FIELD INSPECTION FORM**Loc ID 334740 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292167	WELL	SI	11/01/2022	GW	045-14609	SCHWARTZ 11-2A (O2E)	SI
292168	WELL	PR	01/25/2008	GW	045-14608	SCHWARTZ 2-15A (O2E)	PR
292172	WELL	PR	06/05/2008	GW	045-14615	SCHWARTZ 11-3B (O2E)	PR
292173	WELL	SI	12/01/2022	GW	045-14614	SCHWARTZ 2-14A (O2E)	SI
292448	WELL	PR	06/03/2008	GW	045-14726	SCHWARTZ 2-14D (O2E)	PR

**General Comment:****ECMC Inspection Report Summary**

On Tuesday 10/11/2023, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus O2, at Location # 334740 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Cut slope still shows signs of erosion
  2. One chemical tank labeling is illegible
- Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	One chemical tank labeling is illegible		
Corrective Action:	Provide proper labeling	Date:	10/27/2023
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		
		Date:

**Inspected Facilities**Facility ID: 292167 Type: WELL API Number: 045-14609 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced 11/2022

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 292168 Type: WELL API Number: 045-14608 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 292172 Type: WELL API Number: 045-14615 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 292173 Type: WELL API Number: 045-14614 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last produced 12/2022

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 292448 Type: WELL API Number: 045-14726 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
Berms						

Comment: 1. Cut slope still shows signs of erosion

Corrective Action: Install, maintain or repair required BMPs

Date: 11/17/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403560898	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6284402">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6284402</a>
707800673	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6284379">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6284379</a>