

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2023

Submitted Date:

10/04/2023

Document Number:

712700693

FIELD INSPECTION FORMLoc ID 333517 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10734

Name of Operator: HIGH RIVER RESOURCES OPERATING LLC

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@highriverllc.com	All Inspections
Vaughn, Robert		rvaughn@highriverllc.co	Primary Contact
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214279	WELL	PR	10/01/2019	GW	067-05614	BONDAD 34-10 1-36	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700520 submitted 8/14/2023.

Equipment inventory listed on previous inspection, no change in equipment on location.

New corrective actions identified.

Location					
Lease Road:					
Type	Access				
comment:	Private road to multiple locations and facilities.				
Corrective Action					Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	TANK LABELS/PLACARDS				
Comment:	Contents and volume labeling, NFPA placards on produced water tanks.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Metal sign posted on separator. Wellhead is positioned approximately 100 ft from process equipment and is not clearly identified/marked as to ownership.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Posted on wellhead sign.				
Corrective Action:					Date: _____
Good Housekeeping:					
Type	OTHER				
Comment:	Impacted material on ground at skid mounted compressor. Impacted area approximately 10-ft. x 5-ft. See Photos #2-#4.				
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D.				Date: 10/09/2023
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: _____					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	TANK BATTERY				
Comment:	T-post and hog wire surrounding 20 bbl produced water tank.				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		37.144630,-107.881440
Comment: Screened, open top steel tank, labeled 60 bbls.					
Corrective Action:					Date:
Paint					
Condition	Adequate				

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Plastic liner does not cover the entire base of the containment. See Photo #5.			
Corrective Action:	Install liner material to ensure spill or released materials will be maintained with containment structure.			Date: 11/04/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	214279	Type:	WELL	API Number:	067-05614	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	08/10/2023	Annual Brhd Completed?	Yes						
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:	NONE					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Ditches	Pass	Material Handling And Spill Prevention	Pass	Container within containment.

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403550068	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273574
712700700	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273566