

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2023

Submitted Date:

10/14/2023

Document Number:

708901960

FIELD INSPECTION FORM

Loc ID 311612 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 32 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269872	WELL	PR	07/02/2012	GW	045-09416	LAST DANCE 12-2	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 10/10/2023 at approximately 11:57 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC LAST DANCE 12-2 Pad. Location # 311612 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Unmarked deadman with a CA date of 10/28/2023
2. Housekeeping - Unused equipment on location with a CA date of 11/13/2023
3. Signs/Marker - Methanol tanks lack required information with a CA date of 11/13/2023
4. Stormwater - Erosion & transport of sediment off location & erosion & lack of stabilization on slope with a CA date of 10/29/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
This is a summary of inspection report.

Dual lease, shared facilities with Last Dance 13B, location # 334763

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	2 methanol tanks lack required information & labeling is falling off		
Corrective Action:	Comply with Rule 605, fix labels & add required information		Date: 11/13/2023
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location - ECD is disconnected & not in use		
Corrective Action:	The storage of equipment not necessary for use on location is prohibited.		Date: 11/13/2023
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig station - Cattle panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank - Cattle panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Pig Station	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	1 marked deadman & 1 unmarked deadman		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.		Date: 10/28/2023
Type: Emission Control Device	# 1		

Comment:	ECD is disconnected & not in use		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Last dance Caerus piggyback		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 10			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 3			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	Separate containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	HEATED STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLs	STEEL AST		,	
Comment:	Separate containment					
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)	500 gal					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient			
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	200 BBLs	HEATED STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate					
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 269872 Type: WELL API Number: 045-09416 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction in some areas
		Compaction				
Other	Fail					Erosion & lack of stabilization on slope
		Ditches				
		Gravel				Sparse in sections
		Culverts				
Gravel						Sparse in areas
Other	Fail					Erosion & transport of sediment off location
Berms						
Ditches						
				Material Handling And Spill Prevention		Chemical tank containment

Comment: [1. Erosion & transport of sediment off location](#)
[2. Erosion & lack of stabilization on slope](#)

Corrective Action: **Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.**

Date: 10/29/2023

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Signs/Marker, Housekeeping, Equipment & Stormwater for observed compliance issues.	smelserw	10/14/2023
Dual lease, shared facilities with Last Dance 13B, location # 334763		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403561088	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6284889
708901961	Inspection 708901960 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6284885
708901962	Inspection 708901960 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6284886