

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2023

Submitted Date:

10/18/2023

Document Number:

712700765**FIELD INSPECTION FORM**Loc ID 306961 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74650Name of Operator: RIM OPERATING INCAddress: 5 INVERNESS DRIVE EASTCity: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:27 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rector, Libby	720-221-1675	Lrector@rimop.com	SW Inspection Reports
Rector, Mike	720-221-1677	mhr@rimop.com	SW Inspection Reports
Elledge, Randy	505-320-4969	relledge@rimop.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285275	WELL	PR	03/10/2007	CBM	067-09185	PARGIN RANCH 1	PR

General Comment:[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

Location

Lease Road:			
Type	Access		
comment:	Long access through ongoing agricultural operations.		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume labels, NFPA placards on produced water tanks.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Contents labels.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted at pumpjack fencing.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24 hour operator contact number is posted, well location signage missing local emergency services number.

Corrective Action: Post local emergency services number or 911 on well location signage.

Date: 11/17/2023

Good Housekeeping:

Type	WEEDS		
Comment:	Kochia encroaching on east side of location.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Angle iron around pumpjack.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Pipe rail and hog wire around produced water tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe rail and hog wire around pumpjack and wellhead.		
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:	Pipe rail and hog wire around separator.			
Corrective Action:			Date:	
Type	OTHER			
Comment:	T-posts around cathodic protection and solar panel.			
Corrective Action:			Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	3" line from separator to digital meter. Calibration date 5/11/2022.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 11/17/2023
Type: Other	# 2		
Comment:	Chemical additive container, lube oil container.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry, cathodic protection.		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	3" line from wellhead to separator. 1" line from separator to tank heater. 1" line from separator to prime mover.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:	On separator vent stack. On tank heater vent stack.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas motor		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	Open Top		37.062130,-107.559710	
Comment:	Partially buried, screened open top steel tank, labeled 95 bbl.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Cellar vault lined with corrugated metal.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		37.062200,-107.559520	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	285275	Type:	WELL	API Number:	067-09185	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/04/2023	Annual Brhd Completed?	Yes						
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Containers within containment.
Compaction	Pass	Ditches	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403564139	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6288136
712700768	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6288133