

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2023

Submitted Date:

10/26/2023

Document Number:

699107700**FIELD INSPECTION FORM**Loc ID 317489 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
317489	LOCATION	AC			-	SHOE-62N62W 21SWSE	SI

**General Comment:**[This is an AMI to FIRR #403565313. 1 out of 3 CA's were corrected.](#)

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

#

Comment: No gas meter run calibration card.

Corrective Action: Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).

Date: 09/22/2023

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment: Berms around the production tank are weathered.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 09/22/2023

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 317489 Type: LOCATION API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 10/26/23 at approximately 1130hrs I, Inspector Adam Burns, Conducted an AML inspection to FIRR #403565313 at Shoe-62N62W 21SWSE Tank Battery of KP Kauffman Company Inc. Location ID #317489 in Weld County, Colorado.</p> <p>1 out of 3 CA's were corrected</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>No gas meter run calibration card. Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2). With a Corrective Action date of 9/22/23</p> <p>Berms around the production tank are weathered. Repair or install berms or other secondary containment devices per Rule 603.o. With a Corrective Action date of 9/22/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	10/26/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107701	KPK photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6299350">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6299350</a>
699107702	KPKP photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6299351">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6299351</a>