

# Construction and Stormwater Inspection

October 24, 2023

Operator: BISON IV OPERATING LLC- 10670

Location ID: 477204

Inspection Document #: 697504910

Weld County, CO

NESE Section 29 T8N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ancona/Pad  
Location ID: 477204



**Photo 1.** Photo taken from the entrance of location, facing East. Photo illustrates a tracking device BMP installed. At the time of this inspection, the BMP was in proper functioning condition.



**Photo 2.** Photo taken from the entrance of location, facing Northeast. Photo illustrates inlet culvert protection. However, there was erosion observed along the roadside ditch area.

Note- the mailbox has the required permits.

Inspection Photos  
Location Name: Ancona/Pad  
Location ID: 477204



**Photo 3.** Photo taken from the entrance of location, facing North. Photo illustrates stormwater erosion which needs additional BMPs and repairs.



**Photo 4.** Photo taken from Photo 3, facing West. Photo illustrates sediment accumulation in the roadside ditch areas.

Inspection Photos  
Location Name: Ancona/Pad  
Location ID: 477204



**Photo 5.** Photo taken from the southeastern perimeter of location, facing South. Photo illustrates desirable vegetation establishment which is in process of meeting vegetation requirements.



**Photo 6.** Photo taken from the topsoil stockpile, facing West. Photo illustrates desirable vegetation establishment which is in process of meeting vegetation requirements.

Inspection Photos  
Location Name: Ancona/Pad  
Location ID: 477204



**Photo 7.** Photo taken from the southeastern location on the topsoil stockpile, facing Southeast. Photo illustrates Operator has installed a perimeter ditch BMP in response to the previous corrective action.

Photo illustrates some erosion in the ditch BMP that needs additional stabilization and repair. Sediment accumulation is shown in Photo 8.



**Photo 8.** Photo taken from the southeastern location on the topsoil stockpile, facing West. See comments under Photo 7.

Filtrexx wattle BMP has also been installed in addition to the ditch BMP. Sediment accumulation is evident from the ditch BMP that needs additional stabilization.

Inspection Photos  
Location Name: Ancona/Pad  
Location ID: 477204



**Photo 9.** Photo taken from the southwestern portion of the location, facing West. Photo illustrates a detention area that is in proper functioning condition.

Note- there is some rill erosion going into the detention area needing additional stabilization. Filtrexx wattle BMP has also been installed along the western perimeter of the location.



**Photo 10.** Photo taken from southwestern location, facing East. Photo illustrates the well pad surface. Operator has added additional stabilization around the wellheads but the remainder of the well location may need additional stabilization during drilling operations depending on time of the year.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504910