

Inspection Photos
Location: Drill Site 3
Facility ID: 333348



Photo 1 –Wellhead Placard SMU 6-15-I



Photo 2 – Spill Remediation # 31510, Spill ID # 484278

Inspection Photos
Location: Drill Site 3
Facility ID: 333348



Photo 3 – Drill Site # 3 Overview

Photo 4 – SMU 4-23-L No well placard at Wellhead

Inspection Photos
Location: Drill Site 3
Facility ID: 333348





Photo 5 – 4-23-L Oil Stained soil

Photo 6 – 4-23-L Oil Stained soil

Inspection Photos
Location: Drill Site 3
Facility ID: 333348



Photo 7 – SMU 3-23-D



Photo 8 – 3-23-D Wellhead

Inspection Photos
Location: Drill Site 3
Facility ID: 333348




Photo 9 – 3-23-D Oil Stained Soil

Photo 10 – 3-23-D Oil Stained Soil