

Inspection Photos  
Location: Drill Site  
Facility ID: 334553



Photo 1 –Wellhead Placard SMU 4-4-P P&A  
Wellhead



Photo 2 – SMU 4-4-P Cemented Wellhead,  
Remediation # 24086

Inspection Photos  
Location: Drill Site  
Facility ID: 334553



**Photo 3 – SMU 4-4-P Cemented Wellhead,  
Remediation # 24086**

**Photo 4 – SMU 4-4-P Cemented Wellhead,  
Remediation # 24086**



Inspection Photos  
Location: Drill Site  
Facility ID: 334553



**Photo 5 – Contaminated Soil**

**Photo 6 – Contaminated Soil**

**Inspection Photos**  
**Location: Drill Site**  
**Facility ID: 334553**



**Photo 7 – Stockpiled backfill material**

**Photo 8 – Drill Site 1 South Pit Facility 483528;  
Remediation # 28196**



Inspection Photos  
Location: Drill Site  
Facility ID: 334553



**Photo 9 – Drill Site 1 South Pit Facility 483528 Fence  
in disrepair**

**Photo 10 – Drill Site 1 North Pit Facility ID 483530;  
Remediation # 28194**