

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



**Photo 1 –Exposed Gathering Line @ 37.214012;
-104.962963 Box Canyon Creek Crossing**

Photo 2 – Exposed Gas Gathering Line

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 3 – Erosion and buildup debris around Drip

Photo 4 – Erosion and buildup debris around Drip

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 5 – Debris buildup around drop from storm event

Photo 6 – Area starting to wash, loose debris from storm event

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 7 – Fill slope of road starting to wash.

Photo 8 – Plugged Culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 9 – Plugged Culvert

Photo 10 – Plugged Culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260




Photo 11 – Half Plugged Culvert




Photo 12 – Half Plugged Culvert, Loos sediment at inlet of culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 13 – Half Plugged Culvert

Photo 14 – Plugged Culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 15 – Half Plugged Culvert

Photo 16 – Half Plugged Culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 17 – Half Plugged Culvert



Photo 18 – Plugged culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 19 – Plugged culvert

Photo 20 – Plugged culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 21 – Half Plugged Culvert

Photo 22 – Fencing around Equipment in disrepair

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 23 – Plugged culvert

Photo 24 – Plugged culvert

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 25 – Erosion, Outlet of culvert

Photo 26 – Half Plugged Culvert



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location: Larissa 32-35
Facility ID: 422584
to Flashback Deep 22-27
Location ID 309260



Photo 27 – Erosion, Outlet of culvert