


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Location is within
Rule 411a Surface Water External Buffer. Location is within
close proximity to Rule 411.b Generalized External Buffer.**

Section/Township/Range: 9 7S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452




North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4688 Failure to minimize surface disturbance



Photo # 4689 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4690 Failure to minimize surface disturbance



Photo # 4691 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4692 Failure to minimize surface disturbance



Photo # 4693 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4694 Failure to minimize surface disturbance



Photo # 4695 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4696 Failure to minimize surface disturbance



Photo # 4697 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4698 Failure to minimize surface disturbance



Photo # 4699 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4700 Failure to minimize surface disturbance



Photo # 4701 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4702 Failure to minimize surface disturbance



Photo # 4703 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4704 Failure to minimize surface disturbance



Photo # 4705 Failure to minimize surface disturbance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4706 Lack of stabilization/compaction/insufficient BMP's



Photo # 4707 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452




Photo # 4708 Lack of stabilization/compaction/insufficient BMP's



Photo # 4709 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4710 Lack of stabilization/compaction/insufficient BMP's



Photo # 4711 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4712 Lack of stabilization/compaction/insufficient BMP's



Photo # 4713 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4714 Lack of stabilization/compaction/insufficient BMP's



Photo # 4715 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4716 Lack of stabilization/compaction/insufficient BMP's



Photo # 4717 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4718 Lack of stabilization/compaction/insufficient BMP's



Photo # 4719 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4720 Lack of stabilization/compaction/insufficient BMP's



Photo # 4721 Lack of stabilization/compaction/insufficient BMP's

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE PA 21-9 Pad
Location ID: 324452



Photo # 4722 Lack of stabilization/compaction/insufficient BMP's



Photo # 4723 Lack of stabilization/compaction/insufficient BMP's