

Final Reclamation and Stormwater Inspection

Date: 10/17/2023

Operator: Fundare Resources Operating Company
LLC - 10773

Location ID: 330673

Inspection Document #: 713900039

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Motis 2
Location ID: 330673



Photo 1. Photo taken from the Eastern access road facing West. Representative photo of the access road to the well locations. The access road outline was still apparent, i.e. not dominated by blue grama.

Inspection Photos
Location Name: Motis 2
Location ID: 330673



Photo 2. Photo taken from the East side of the well location facing West. The photo illustrates that the facility outline is still apparent on the landscape being dominated by bare soil, western wheatgrass and russian thistle.

Inspection Photos
Location Name: Motis 2
Location ID: 330673



Photo 3. Photo taken from the well location facing North. The photo illustrates representative debris spread across the location.

Inspection Photos
Location Name: Motis 2
Location ID: 330673



Photo 4. Photo taken from the well location facing Southwest. The photo illustrates russian thistle and kochia growing abundantly onsite as well as bare soil.

Inspection Photos
Location Name: Motis 2
Location ID: 330673



Photo 5. Photo taken at the well location facing South. The photo illustrates the tank battery area is dominated by saltgrass and bare soil.

Inspection Photos
Location Name: Motis 2
Location ID: 330673



Photo 6. Photo was taken on the well location facing South. The photo illustrates there is not uniform vegetative cover on the location representative of reference areas.

Inspection Photos
Location Name: Motis 2
Location ID: 330673



Photo 7. Reference photo was taken on the well location facing off the location Southeast. The photo illustrates blue grama dominated rangeland with pockets of four-winged saltbush.