

Interim Reclamation and Stormwater Inspection

Date: 10/26/2023

Operator: FUNDARE RESOURCES OPERATING
COMPANY LLC - 10773

Location ID: 445579

Inspection Document #: 708200653

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 1. Taken from the eastern side of the location at the southern portion of the topsoil stockpile. Photo illustrates that the topsoil stockpile is not progressing towards Rule 1003 standards with non-uniform vegetative cover resulting in bare and exposed soils. Undesirable vegetation (e.g. kochia and russian thistle) was also observed throughout.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 2. Close up photo of the topsoil stockpile.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photos 3 & 4. Taken from the southeast corner of the location, near the topsoil stockpile. Photo illustrates that soils are not properly stabilized as evidenced by non-uniform vegetative cover.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 5. Taken from the northern portion of the topsoil stockpile. See comments in Photo 1.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 6. Taken from the northern portion of the location. Photo illustrates an area of non-uniform vegetative cover resulting in bare/exposed soils.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 7. Taken from the northern portion, between the topsoil stockpile and the well location. Photo illustrates that portions of the interim reclaimed areas are progressing towards Rule 1003 with desirable species present (blue grama, western wheat, etc).

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 8. Taken from the southern/middle portion of the interim reclaimed area, between the topsoil stockpile and the well location. Photo illustrates that exposed soils are present. Additional revegetation activities are required.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 9. Taken from the western side of the location. Non-uniform vegetative cover resulting in bare soils and trash/debris present.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 10. Western side of the location, see comments in Photo 9.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 11. Western side of the location, see comments in Photo 9.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 12. Northwest side of the location, see comments in Photo 9.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 13. Taken from the northwest corner of the location. Evidence of bare and exposed soils.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 14. Taken from the west side of the well location. Photo illustrates that exposed soils are present. Additional revegetation activities are required.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 15. See comments in Photo 14.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 16. Taken south of the well location. Photo illustrates that exposed soils are present. Additional revegetation activities are required. Also pictured, trash/debris (red arrow).

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 17. Continued from Photo 16. See comments in previous photo.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 18. Concrete foundation does not appear to be in use and must be removed per Rule 606.

Inspection Photos
Location Name: Horsetail 30H Pad
Location ID: 445579



Photo 19. Jersey barriers on the well location do not appear to be in use and must be removed per Rule 606.