

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-3C (C9W) Pad

Location #: 334615



Photo # 4984 From entrance to location



Photo # 4985 From entrance to location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-3C (C9W) Pad

Location #: 334615




Photo # 4986 Location

Photo # 4987 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-3C (C9W) Pad

Location #: 334615



Photo # 4988 Location



Photo # 4989 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-3C (C9W) Pad

Location #: 334615



Photo # 4990 Location



Photo # 4991 Holes in liner/liner needs maintenance

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-3C (C9W) Pad

Location #: 334615



**Photo # 4992 Holes in liner/liner needs maintenance**



**Photo # 4993 Hole in liner/liner needs maintenance**