

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2023

Submitted Date:

11/01/2023

Document Number:

712700812

FIELD INSPECTION FORMLoc ID 326596 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|----------------------------------|--------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | Regulatory@logosresourcesllc.com | All SW Inspections |
| Fields, Vanessa | | vfields@logosresourcesllc.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 258578 | WELL | PR | 08/09/2001 | GW | 067-08368 | BONDAD 33-10 17A | PR |

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

| Location | | | | |
|--|---|--------|--|-----------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Access from CR 213, through neighborhood. | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Volume and contents label, NFPA placard. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Metal sign posted at produced water tank. | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | 24 hour operator contact number and 911 local emergency number posted on well location signage. | | | |
| Corrective Action: | | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: <input type="text"/> | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | OTHER | | | |
| Comment: | Sound abatement walls around skid mount compressor. | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| | | | | corrective date |
| Type: Bird Protectors | # 2 | | | |
| Comment: | On separator vent stacks. | | | |
| Corrective Action: | | | | Date: |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Wellhead | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | Digital meter unitized with separator/dehydrator. Calibration date 6/21/023. | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | # 1 | | | |
| Comment: | Accessible | | | |
| Corrective Action: | | | | Date: |

| | | |
|-----------------------------------|--|------------------|
| Type: Deadman # & Marked | # 4 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Dehydrator | # 1 | |
| Comment: | Unitized with skid mount horizontal heated separator and metering. | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Compressor | # 1 | |
| Comment: | Skid mount. Observed impacted material on ground below containment pan. See photo #6. | |
| Corrective Action: | Conduct maintenance on equipment, cleanup stained material and increase self inspection processes. | Date: 11/16/2023 |
| Type: Flow Line | # 2 | |
| Comment: | 2-2" lines from wellhead to separator. 1-2" line from separator to skid compressor. | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 200 BBLs | Open Top | | 37.107370,-107.901310 |
| Comment: | Partially buried, screened open top steel tank labeled 125 bbl. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-------------------------|----------------------------|------------------------|-------------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 258578 | Type: | WELL | API Number: | 067-08368 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 08/22/2023 | Annual Brhd Completed? | Yes | | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 31 | Fluid Type: | | | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Compaction | Pass | Ditches | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |
| Berms | Pass | Culverts | Pass | Material Handling And Spill Prevention | Pass | Container within containment. |

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 712700817 | INSPECTION PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306606 |