

# Work Completion Report

Contractor: Peerless

## JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
UIV 18-20		Armando Munoz	10/25/2023

Work Summary	Reclamation Type	Land Use
Repaired the erosion on the SW corner of the tank battery.	Stormwater	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

## WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	High	Yes	Location(s): UIV 18-20 Notes: Address and repair erosion on SW corner of TB.

## COMPLETION DETAILS

Total Area Affected: **0.15 acres**  
 Seed Mix: **None used**  
 Crop Type:  
 Soil Type: **Clay Loam**  
 Stabilization Date: **10/25/2023**  
 Seeding Date:  
 Mulch: **None**  
 Straw Bales: **NA**  
 Soil Amendment Type: **None**  
 Soil Amendment Rate: **NA**  
 Imported Top Soil: **NA**  
 Top Soil Source: **NA**  
 General Notes:

LOCATION INFO

---

Location(s) – Name: UIV 18-20

COGCC ID: **306059**

Well APIs at Location: **12323926**

Land Rep:

Land Owner:

Rec Contractor PO(s): **M&E - 4501631809**

Vendor PO(s):

Billing Notes: **DJ-L0417**

Legal Address: **(WELD) NWNW 20 5N67W**

Topsoil Source:

Variance Notes:

Private Utility Notes:

Wildlife Restrictions:

General Notes:

COGCC Doc #'s:

Initial Reclaim Complete Date:

Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map  
Description:



Photo Name: Site Map 2  
Description:

Photo Name: Pre-Completion

Description:




Photo Name: Post-Completion

Description:



Photo Name: UIV1

Description:



Photo Name: UIV2

Description:



Photo Name: UIV3

Description:



Photo Name: UIV4

Description:

