

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102



Photo # 5164 From entrance to location



Photo # 5165 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102



Photo # 5166 Location



Photo # 5167 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102



Photo # 5168 Location



Photo # 5169 PRV & Rupture disc vent lines lack caps

Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 207-20 Pad

Location # 324102




Photo # 5170 PRV & Rupture disc vent lines lack caps