

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2023

Submitted Date:

11/03/2023

Document Number:

712700823**FIELD INSPECTION FORM**Loc ID 326199 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**24 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216026	WELL	PR	10/02/2014	CBM	067-07632	TUBBS 32-6-9 B 1	PR

**General Comment:**SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access from CR 330, long private road.		
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	NFPA placard on separator and meterhouse.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Label on container.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted at wellhead/pumpjack enclosure.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Observed equipment stored/not in use on pad and on reclamation area which appears to be landowner related, no approved variance in well file.		
Corrective Action:	Remove all unused equipment unless a variance per rule 606.a(2) is approved.		Date: 01/02/2024
Type	OTHER		
Comment:	Observed impacted material on ground at prime mover exhaust. See photo #6.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and increase self-inspection intervals.		Date: 11/20/2023
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	Cattle panel around meterhouse.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Cattle panel around telemetry.		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	<a href="#">Cattle panel enclosure around wellhead and pumpjack.</a>		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	<a href="#">Cattle panel enclosure.</a>		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	<a href="#">Pipe rail around weights.</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	<a href="#">Natural gas motor</a>		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	<a href="#">PVC access</a>		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	<a href="#">Lube oil container.</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	<a href="#">On separator vent stack.</a>		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	<a href="#">2" line from separator to meterhouse. Calibration date</a>		
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	<a href="#">3" line from wellhead to separator. 1" line from separator to prime mover.</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	<a href="#">Telemetry</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Wellhead</a>		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	216026	Type:	WELL	API Number:	067-07632	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	03/10/2023	Annual Brhd Completed?	Yes						
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Ditches	Pass	Ditches	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700831	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308757</a>