

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2023

Submitted Date:

11/05/2023

Document Number:

698601231**FIELD INSPECTION FORM**Loc ID 302946 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 270676 | WELL | PR | 04/21/2004 | GW | 125-02362 | MEKELBURG FARMS 2-7 | PR |

General Comment:

Routine Inspection.

Location

| | | | |
|--------------------|------------------------------------------------------------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road. Active agricultural cropland with seasonal access. | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|-------------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well sign located inside well fencing | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Well sign posted at remote gas meter run. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--------------------------------------------------------------------------------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Emergency contact information posted on both the Well location and Meter Shed signs. | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------------------------------------------------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Stock panel fencing around surface equipment at well site. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------------------------------------------------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Prime Mover | # 1 | | |
| Comment: | Gas fired Motor. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead plumbed to surface. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Rods and tubing in the wellbore. Tubing valve open. Casing valve open. | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Meter Shed at remote Gas Meter Run. | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|
| Type: Gas Meter Run | # 1 | |
| Comment: | Remote Gas Meter Run located on CR O at the 125-08293 meter location. Digital Gas Meter Run. Meter Calibration/Test Log dated 1-27-23. Well Inlet Valve open. Gas Outlet Valve open. | |
| Corrective Action: | | Date: |
| Type: Dehydrator | # 1 | |
| Comment: | Dehydrator on gas meter run inlet. | |
| Corrective Action: | | Date: |
| Type: Other | # 1 | |
| Comment: | Pump Jack Cement Pad. | |
| Corrective Action: | | Date: |
| Type: Pump Jack | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 1 | |
| Comment: | Pump Jack Power and Control Panel. | |
| Corrective Action: | | Date: |
| Type: Dehydrator | # 1 | |
| Comment: | Supply gas line for prime mover. | |
| Corrective Action: | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 270676 | Type: | WELL | API Number: | 125-02362 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Electronic Well File reflects last Production/Status reported 8/1/2023 and Well Status as PR. Based on current valve settings the well is PR. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 698601266 | Inspection photos. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310458 |