

Inspection Photos

Loc: 320988

Operator: **DOVER ATWOOD CORPORATION**

Inspection Date: 10/31/2023

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the access road. There is erosion along the road that needs to be repaired and stabilized..



Inspection Photos



Photo 2. Facing northeast toward the wellsite.



Inspection Photos



Photo 3. There is no secondary containment around the open top tank. The fence around the equipment is in disrepair and the cattle panel is laying on the ground.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320988 | Date: 10/31/2023

Inspection Photos



Photo 4. There is no secondary containment around the open top tank. The fence around the equipment is in disrepair.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:320988 | Date: 10/31/2023

Inspection Photos



Photo 5. Facing toward the pumpjack. The fence around the equipment is in disrepair and the cattle panel is laying on the ground.

