

# Inspection Photos

Loc: 429852

Operator: **DOVER ATWOOD CORPORATION**

Inspection Date: 10/31/2023

County: BACA



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the Walsh/Bishop Gas Compressor. There is weeds and dry vegetation around the equipment which is a fire hazard.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:429852 | Date: 10/31/2023

## Inspection Photos



**Photo 2.** Facing northwest toward the Walsh/Bishop Gas Compressor. There is weeds and dry vegetation around the equipment which is a fire hazard.





## Inspection Photos



**Photo 3.** The wall behind the compressor engine is leaning over about to fall down.



## Inspection Photos



**Photo 4.** There is green liquid glycol I the engine skid that must be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:429852 | Date: 10/31/2023



## Inspection Photos



**Photo 5.** There is no secondary containment at the chemical tote.



## Inspection Photos



**Photo 6.** There are weeds around the open top tank and insufficient secondary containment.





## Inspection Photos



**Photo 7.** Facing southwest at the location which is located off a busy County Road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:429852 | Date: 10/31/2023



## Inspection Photos



**Photo 8.** Facing toward the separator. There is no secondary containment and the location sign is obscured by weed cover.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:429852 | Date: 10/31/2023