

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2023

Submitted Date:

11/07/2023

Document Number:

713600353

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 7 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
Crane, Shaun	719-353-2526	cimbaca.production.services@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429852	GAS COMPRESSOR STATION	AC			-	Walsh/Bishop Gas Compressor	RI

General Comment:

On 10/31/2023, Ryan Costa conducted an inspection at the Walsh/Bishop Gas Compressor Location. See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:

Type			
Comment:	The location sign is obscured by weeds. The QTR QTR and section is not accurate on the sign. Corrective action will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605	Date:	10/31/2023

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	The metal wall behind the engine skid is leaning and could fall over. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with 608 for maintenance on equipment.	Date:	10/31/2023
Type	WEEDS		
Comment:	There are weeds and dry vegetation debris around the equipment which is a fire hazard. The weeds around the location need to be controlled and debris removed. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	10/31/2023

Overall Good:

Spills:

Type	Area	Volume	
Glycol			
Comment:	There is glycol spilled in the engine compressor skid that needs to be cleaned up. Corrective action will remain out of compliance until completed.		
Corrective Action:	Immediately Clean up spilled glycol per Rule 906 and 1002f Material Handling and Spill Prevention.	Date:	10/31/2023

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	2				
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	The berm around the open top tank is insufficient to contain a spill and has weeds growing which can compromise permeability. There is also no secondary containment at the separator. Corrective action will remain out of compliance until completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	10/31/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		

Comment: There is no secondary containment for the chemical tote.

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention.

Date: 10/31/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600354	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313525