

Inspection Photos

Loc: 320973

Operator: **DOVER ATWOOD CORPORATION**

Inspection Date: 10/31/2023

County: BACA



Loc:320973 | Date: 10/31/2023

Inspection Photos



Photo 1. Facing northwest toward the wellsite.



Inspection Photos



Photo 2. There is a broken pipe at red arrow and weeds around the equipment.



Inspection Photos



Photo 3. The fence around the pumpjack is in disrepair.



Inspection Photos



Photo 4. The sign posted at the well is faded and does not meet the requirements.



Inspection Photos



Photo 5. Facing toward the separator. There is no containment around the separator.



Inspection Photos



Photo 5. Facing toward the tank. There are weeds around the tank that are a fire hazard. Secondary containment is insufficient. And the labeling is faded.

