

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2023

Submitted Date:

11/07/2023

Document Number:

705000504

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Maclaren, Joe \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, John		jpeterson@kpk.com	
Graber, Nikki		nikki.graber@state.co.us	
KPK		cogcc@kpk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242965	WELL	PR		OW	123-10756	OWEN 12-1	PR
479346	OFF-LOCATION FLOWLINE	AC	02/10/2021		-	Wellhead Line 11-33HN	EG

**General Comment:**

COGCC Engineering Integrity Inspection performed on November 3rd, 2023 in response to initial form 19 spill report Doc #403575341 received on 10/29/2023 that outlines: On Oct 26, 2023, the landowner contacted KPK about oil release at the ground surface. KPK immediately responded and isolated and blew down the flow line to the Owen 12-1 wellhead. KPK initiated excavation of the impacted soil and transported it offsite for disposal at the Front Range Landfill. The cause of the release is unknown at this time but is believed to be from corrosion of the buried steel pipe. The amount released is unknown but is estimated at 1-5 barrels at this time.

Corrective Actions identified during this field inspection are outlined in the flowline section of report. Photos uploaded.

## Inspected Facilities

Facility ID: 242965 Type: WELL API Number: 123-10756 Status: PR Insp. Status: PR

## Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

## Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel  
 Variance: No Age: Contents: Crude Oil

## Integrity Summary

Failures: Spills: Yes Repairs Made:  
 Coatings: H2S: Cathodic Protection:

## Pressure Testing

Witnessed: Test Result: Charted:

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

**Comment:** COGCC Integrity Inspector on site on 11/03/2023. An open excavation (measuring approx 10' x 15') was observed @ 40.235212, -104.957389. (1) 2" OD CS OLF flowline was observed exposed in the excavation. The flowline failure was not observed/ identified during this field inspection; no flowline repair work was found (clamps, welded pipe etc) on the exposed portion of pipe. The status of the flowline failure/ repair work is unknown at this time. The Owen 12-1 well was producing at the time of inspection. Excavation/ remediation work in progress.

**Corrective Action:** Document information requested below in the CA section of COGCC supplemental form 19 spill report to include the following (compliance of COGCC series 1100 flowline rules):  
 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/Operator Determination)  
 2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control/ 1104. Integrity Management)  
 3) Description of flowline repair work completed (1102.j. Repair)  
 4) Confirm integrity of flowline repairs/ reconnections (via pressure testing/ upload chart with test date) prior to returning flowline(s) to service (1102.j.4 and 1102.O)

Date: 11/17/2023

\*use form 27 to document information if form 19 is closed

Facility ID: 479346 Type: OFF- API Number: - Status: AC Insp. Status: EG

## Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000506	Signage at wellhead; view W	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314200">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314200</a>
705000507	View S from well to battery; OLF spill fenced	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314201">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314201</a>
705000508	WH flowline exposed in excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314202">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314202</a>