

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2023

Submitted Date:

11/01/2023

Document Number:

712700813

**FIELD INSPECTION FORM**

Loc ID 326100 Inspector Name: Pattillo, Curtis On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

22 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All SW Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215866	WELL	PR	07/15/2009	CBM	067-07471	PRESENTACION MEDINA A 1	PR

**General Comment:**

[SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Access from CR 213. Locked gate, 2C40 key.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Warning signs on separator, pumpjack.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Contents and volume label, NFPA placard on produced water tank.		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Observed impacted material on ground at the wellhead. See photo #5.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and increase self inspection processes.		Date: 11/16/2023
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Cattle panel around separator, produced water tank, electrical service boxes.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	T-post and barbed wire.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal mesh cage.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	3" line, unitized with separator. Calibration date 7/27/2023.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	PVC access		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Telemetry, electrical control box, electrical service box.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:	Unitized with metering.		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	1-3" line from wellhead to separator. 1-1" line from separator to wellhead.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Chemical additive container.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV STEEL		37.114000,-107.899810	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 215866 Type: WELL API Number: 067-07471 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 06/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Rip Rap	Pass	Ditches	Pass			
Compaction	Pass	Gravel				
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.

Comment: East side and south side fill slopes showing subsidence. Rip/rap is working, needs maintenance, berms re-established. See photos #7-#8.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403579830	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6305168">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6305168</a>
712700818	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6305166">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6305166</a>