

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2023

Submitted Date:

10/27/2023

Document Number:

694100197

FIELD INSPECTION FORMLoc ID 414834 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections
,		COGCCinspections@anadarko.com	All Inspections
Avant, Paul	720-929-6457	paul.avant@anadarko.com	

General Comment:

This is an environmental inspection for Location ID 414834 Horse Iron P 21-27D well pad and tank battery. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

Comment: signs on the ground. Weeds/debris throughout.

Corrective Action: Statewide unnecessary equipment, weeds, waste, and trash requirements. Comply with Rule 606.

Date: 11/10/2023

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type

Comment: Orange construction fencing around several small open excavations needs to be repaired.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/10/2023

Venting:

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Location Construction

Location ID: 414834 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Comment: Soil stock pile at TB is unlined. Needs erosion control bmps to be installed to prevent onsite runoff.**Corrective Action:** Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/10/2023

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

COGCC Comments

Comment	User	Date
This site is part of an ongoing complaint from the landowner. Both landowner and operator are being consulted for the duration of the complaint. This location has an ongoing groundwater project associated with it (project number 23968). The complaint is regarding reclamation progress or lack thereof. Large bare areas are present surrounding the horse iron wellheads. Several soil stock piles are present as well. Groundwater is present in the open cut and capped wellhead excavations. Current cattle fencing at the wellheads is sufficient. ECMC environmental staff will continue to monitor this location as the remediation project progresses and ECMC reclamation staff will be consulted throughout as well.	robinsotl	10/27/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403581667	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306847
694100198	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306838