

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2023

Submitted Date:

10/27/2023

Document Number:

694100201

FIELD INSPECTION FORMLoc ID 323149 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		COGCC@KPK.com	All Inspections
, KPK		cogcc@kpk.com	All Inspections
Teter, Roy		cogcc@kpk.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 323149 Champlin 86 Amoco. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

Comment:

Orange construction fencing around large open excavation is falling down. Needs to be repaired.

Corrective Action:

Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/10/2023**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
This location is currently a part of a complaint. It has a large open excavation with construction fence surrounding it. It is approximately half full with groundwater. There appears to be an open remediation project ongoing at this location to the SW of the excavation. Possibly SVE/AS. See attached photos.	robinsotl	10/27/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403581671	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306849
694100202	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306840