

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2023

Submitted Date:

11/03/2023

Document Number:

712700819

**FIELD INSPECTION FORM**Loc ID 306779 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264621	WELL	PR	11/21/2002	CBM	067-08746	ANDERSON 1 (1R)	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700560 submitted 8/21/2023. All recorded corrective actions have been completed.

Equipment inventory listed on previous inspection, no change to location equipment.  
A new corrective action is recorded, see Housekeeping section.

Location					
<b>Lease Road:</b>					
Type	Access				
comment:	Access from CR 151, through private entrance.				
Corrective Action					Date:
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	TANK LABELS/PLACARDS				
Comment:	Contents and volume label, NFPA placard on produced water tank.				
Corrective Action:					Date:
Type	OTHER				
Comment:	NFPA placard on separator.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Metal sign posted at location entrance.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.				
Corrective Action:					Date:
<b>Good Housekeeping:</b>					
Type	DEBRIS				
Comment:	Corrective action identified in FIR Doc.#712700560 has been completed.				
Corrective Action:					Date:
Type	UNUSED EQUIPMENT				
Comment:	Observed equipment stored/not in use on pad and reclamation area which appears to be landowner related, no approved variance in well file. This issue was reported on previous FIR Doc.#712700560.				
Corrective Action:	Remove all unused equipment unless a variance per rule 606.a(2) is approved.				Date: 01/02/2024
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
				corrective date	
Type: Deadman # & Marked	#				
Comment:	Corrective action identified in Doc.#712700560 is completed. Guy anchors are marked.				
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		37.041740,-107.529250	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:	Corrective action identified in FIR Doc.#712700560 has been completed.					
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	264621	Type:	WELL	API Number:	067-08746	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	06/15/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	2		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Container within containment.
Compaction	Pass	Ditches	Pass			
Ditches	Pass					

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403583520	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308770">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308770</a>
712700827	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308752">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308752</a>