

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2023

Submitted Date:

11/03/2023

Document Number:

712700821

FIELD INSPECTION FORMLoc ID 333339 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kittinger, Eric		ekittinger@mspartners.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273775	WELL	PR	01/05/2005	CBM	067-08976	PADGETT 32-6 4-1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.
The location is co-located with the #4-3 well (067-09494).

Location				
Lease Road:				
Type	Access			
comment:	Access from CR 330, long private road.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Metal sign posted on wellhead/pumpjack enclosure.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Produced water tank NFPA signs are deteriorating and capacity is not legible. See photos #5-#6. This issue was recorded on FIR Doc.#702500121I submitted 6/27/2022.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 12/04/2023
Type	OTHER			
Comment:	Waring signs on pumpjack fencing.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.			
Corrective Action:				Date:
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Equipment truck and trailer parked on location. The adjacent well, #4-3 appears to have ongoing repairs.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	6-ft. chainlink fence around wellhead and pumpjack.			
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:	Pipe rail and hog wire.			
Corrective Action:				Date:
Type	PUMP JACK			

Comment:		Pipe rail enclosure around weights.			
Corrective Action:				Date:	
Equipment:				corrective date	
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors		# 3			
Comment:		On separator vent stack. 2 on tank heater stacks.			
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:		Electric motor			
Corrective Action:				Date:	
Type: Vertical Heated Separator		# 2			
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment		# 1			
Comment:		Wellhead			
Corrective Action:				Date:	
Type: Gas Meter Run		# 1			
Comment:		3" line from separator to meterhouse.			
Corrective Action:				Date:	
Type: Flow Line		# 2			
Comment:		2" line from wellhead to separator. 1" line from separator to wellhead.			
Corrective Action:				Date:	
Type: Deadman # & Marked		# 5			
Comment:		Two unmarked guy anchors.			
Corrective Action:		Adequately mark guy anchors according to Rule 1003, if anchor is no longer serviceable it should be removed as unused equipment.		Date: 11/17/2023	
Type: Ancillary equipment		# 1			
Comment:		Telemetry			
Corrective Action:				Date:	
Type: Bradenhead		# 1			
Comment:		Accessible			
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	HEATED STEEL AST		37.042320,-107.509340
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above**AirsID**

API Number
067-09494

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	273775	Type:	WELL	API Number:	067-08976	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	04/25/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:	NONE				
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403583533	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308779
712700829	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308754