

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2023

Submitted Date:

11/03/2023

Document Number:

714200283

**FIELD INSPECTION FORM**Loc ID 318744 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421674	WELL	SI	05/01/2022	OW	123-33005	THOMASON 5-15	TA
421675	WELL	SI	05/01/2022	OW	123-33006	THOMASON 32-15	TA
421677	WELL	SI	05/01/2022	OW	123-33008	THOMASON 25-15	TA
421686	WELL	SI	05/01/2022	OW	123-33015	THOMASON 4-15	TA
421687	WELL	SI	05/01/2022	OW	123-33016	THOMASON 31-15	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	One water tank does not display legible capacity on signage. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 12/03/2023
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused/disconnected gas meter. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 02/03/2024
Type	DEBRIS		
Comment:	Debris on various areas of location. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 12/03/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	iron		
Corrective Action:			Date:

**Equipment:**

Type: Emission Control Device		# 4		corrective date
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors			# 10	
Comment:				
Corrective Action:			Date:	

Type: Horizontal Heated Separator	# 6	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 5	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 5	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Shares containment with other tanks.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <a href="#">Shares containment with other tanks.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	OTHER	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	537 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 421674 Type: WELL API Number: 123-33005 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action:  Date: Facility ID: 421675 Type: WELL API Number: 123-33006 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action:  Date: Facility ID: 421677 Type: WELL API Number: 123-33008 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action:  Date: Facility ID: 421686 Type: WELL API Number: 123-33015 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action:  Date: Facility ID: 421687 Type: WELL API Number: 123-33016 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; Form 6A in well file.Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Friday, November 3, 2023 at approximately 1100, I, Inspector Brittani Santistevan, conducted an on-site inspection at THOMASON 4-15 (Kerr McGee Oil &amp; Gas Onshore), at location ID: 318744 in WELD COUNTY, Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. It appears one gas meter is not in use. Comply with Rule 606. (Corrective Action Date: February 3, 2024) See attached photo #8, 9.</p> <p>2. It appears one water tank signage does not display a clear and legible capacity. Comply with Rule 605.h. (Corrective Action Date: December 3, 2023) See attached photo #10.</p> <p>3. It appears to be debris on various areas of location. Comply with Rule 606. (Corrective Action Date: December 3, 2023) See attached photo #11-16.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	11/03/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403583801	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308996">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308996</a>
714200284	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308992">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308992</a>