

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/10/2023

Document Number:

708902183**FIELD INSPECTION FORM**

Loc ID 323930	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>18</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211283	WELL	PR	02/17/1996	GW	045-07042	COUEY 32-15 (O32NE)	PR

<b>General Comment:</b> <p>CECMC Inspection Report Summary          On 11/07/2023 at approximately 10:14 hours, I, Compliance Specialist, Wayne Smelser          Conducted an on-site inspection at CAERUS PICEANCE LLC COUEY 32-15 (O32NE) pad.          Location # 323930 in Garfield County Colorado.          Location is within High Priority/Density/NSO/Black Bear Habitat areas.          Location is approximately 57 yards from Mamm Creek.          While there, I observed normal production operations.</p> <p>During this inspection the following compliance issues were observed:</p> <p>1. Stormwater - Erosion &amp; transport of sediment off location with a CA date of 11/25/2023</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.          This is a summary of inspection report.</p>
---

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-2615			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Small amount of weeds in secondary containment			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Plunger Lift	# 1			corrective date
Comment:	Well on plunger lift			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Pressure transducer located bradenhead, bradenhead valve is accessible.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Unlined containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Centralized containment				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		

Comment:	Unlined containment		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	211283	Type:	WELL	API Number:	045-07042	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Erosion & transport of sediment off location
Compaction						Light compaction
Gravel						Sparse in some areas
		Compaction				
		Ditches				
		Culverts				
		Gravel				Sparse in some areas
		Rip Rap				
		Sediment Traps				

Comment: 1. Erosion & transport of sediment off location & into vegetated areas (NE corner of location near tank battery)

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 11/25/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Stormwater for observed compliance issue.	smelserw	11/10/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902184	Inspection 708902183 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318787">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318787</a>
708902185	Inspection 708902183 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318788">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318788</a>