

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2023

Submitted Date:

11/05/2023

Document Number:

698601236**FIELD INSPECTION FORM**Loc ID 304214 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
254205	WELL	PR	11/09/1998	GW	125-08083	J BROPHY 29-27	PR

**General Comment:**

Routine Inspection.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well sign at well location.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted at remote separator shed door.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Label unreadable.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/06/2023

Emergency Contact Number:

Comment:	Emergency contact information posted on both the Well location and Meter Shed signs.	
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve not connected.		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Separator shed at remote facility.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on access road. Digital Gas Meter Run. Meter Calibration/Test Log dated 11-20-22. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Bradenhead plumbed to surface.		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Meter Shed at remote Gas Meter Run.		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:	At remote facility.		Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV FIBERGLASS		,
Comment:	Label unreadable.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)	Label unreadable.	
Other (Capacity)	Label unreadable.	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	254205	Type:	WELL	API Number:	125-08083	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Electronic Well File reflects last Production/Status reported 8/1/2023 and Well Status as PR. Based on current valve settings the well is PR.								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403584817	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310569">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310569</a>
698601273	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310566">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310566</a>