

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 6202 From entrance to location



Photo # 6203 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 6204 Location



Photo # 6205 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad

Location #: 334669



Photo # 6206 Location



Photo # 6207 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SCARBER RO2 Pad
Location #: 334669



Photo # 6208 Location



Photo # 6209 Debris