

Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 11/8/2023



Inspection Photos



Photo 1. Facing northwest along the access road. There are some check dams where stormwater is going around the check dam. BMP maintenance is needed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06219 | Date: 11/8/2023

Inspection Photos



Photo 2. There are several check dams that are in need of maintenance. Red arrow points to where stormwater is eroding around the check dam.



Inspection Photos



Photo 3. Facing north toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 043-06219 | Date: 11/8/2023

Inspection Photos



Photo 4. There is desirable vegetation beginning to establish in the reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 043-06219 | Date: 11/8/2023

Inspection Photos



Photo 5. Facing north toward the location. There are displaced wattles that need to be repaired. Previous corrective action was not completed.



Inspection Photos



Photo 6. The sediment trap at the west side of the location is filled in with sediment.

