

Inspection Photos

API: 043-06231

Operator: AUSCO PETROLEUM INC

Inspection Date: 11/8/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road to the wellsite. There are noxious weeds along the road that need to be controlled. Red arrow points to List B – Halogeton.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 11/8/2023

Inspection Photos



Photo 2. Facing toward the drainage crossing which has been washed out and has not been repaired. Previous corrective action was not completed.



Inspection Photos



Photo 3. View of culvert outlet shows displaced rock. Outlet protection will need to be reinstalled. Previous corrective action was not completed.



Inspection Photos



Photo 4. Facing southwest toward the wellsite. There are undesirable weeds around the equipment that need to be controlled.



Inspection Photos



Photo 5. Facing southwest toward the interim reclamation area. There is mostly undesirable weeds growing throughout this area and the straw wattle is displaced. Previous corrective action was not completed.



Inspection Photos



Photo 6. Facing northwest toward the interim reclamation area. There is entirely undesirable weeds growing throughout this area. This area will need weed control and reseeding. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-06231 | Date: 11/8/2023