

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2023

Submitted Date:

11/07/2023

Document Number:

713600353

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Crane, Shaun	719-353-2526	cimbaca.production.services@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429852	GAS COMPRESSOR STATION	AC			-	Walsh/Bishop Gas Compressor	RI

General Comment:On 10/31/2023, Ryan Costa conducted an inspection at the Walsh/Bishop Gas Compressor Location.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type			
Comment:	The location sign is obscured by weeds. The QTR QTR and section is not accurate on the sign. Corrective action will remain out of compliance until completed.		
Corrective Action:	Install sign to comply with Rule 605	Date:	10/31/2023

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	There are weeds and dry vegetation debris around the equipment which is a fire hazard. The weeds around the location need to be controlled and debris removed. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	10/31/2023
Type	OTHER		
Comment:	The metal wall behind the engine skid is leaning and could fall over. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with 608 for maintenance on equipment.	Date:	10/31/2023

Overall Good: ☐**Spills:**

Type	Area	Volume			
Glycol					
Comment:	There is glycol spilled in the engine compressor skid that needs to be cleaned up. Corrective action will remain out of compliance until completed.				
Corrective Action:	Immediately Clean up spilled glycol per Rule 906 and 1002f Material Handling and Spill Prevention.			Date:	10/31/2023

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	2				
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	The berm around the open top tank is insufficient to contain a spill and has weeds growing which can compromise permeability. There is also no secondary containment at the separator. Corrective action will remain out of compliance until completed.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:	10/31/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		

Comment: There is no secondary containment for the chemical tote.

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention. Date: 10/31/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403587376	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313528
713600354	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6313525