

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location ID: 311543



Photo # 6471 From entrance to location



Photo # 6477 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location ID: 311543



Photo # 6478 Location



Photo # 6479 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location ID: 311543



Photo # 6480 Location



Photo # 6481 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location ID: 311543



Photo # 6482 PRV & rupture disc vent lines lack caps



Photo # 6483 Rupture disc vent line lacks cap

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location ID: 311543



Photo # 6484 PRV vent line lacks cap



Photo # 6485 Observed distortion coming off rupture disc vent line/rupture disc leaking gas

Inspection Photos

Location Name: MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location ID: 311543



Photo # 6488 Debris