

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2023

Submitted Date:

11/14/2023

Document Number:

708902233

**FIELD INSPECTION FORM**Loc ID 311543 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: PO BOX 13550

City: BAKERSFIELD State: CA Zip: 93389

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210685	WELL	PR	07/01/2021	GW	045-06441	CLOUGH FEDERAL 14-24A-6S-94W	PR

**General Comment:****CECMC Inspection Report Summary**

On 11/14/2023 at approximately 10:21 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at MUSTANG RESOURCES LLC CLOUGH FEDERAL 14-24A-6S-94W

Location # 311543 in Garfield County Colorado.

Location is within High Priority/Density Habitat areas &amp; in close proximity to Bald Eagle Roost Site.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Gas meter not calibrated annually with a CA date of 12/14/2023
2. Equipment - Mechanical condition - Rupture disc leaking gas with a CA date of 11/17/2023
3. Equipment - PRV & rupture disc vent lines lack caps with a CA date of 11/21/2023
4. Stormwater - Erosion & transport of sediment with a CA date of 11/29/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/888-291-8588			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	Debris - please refer to photo log			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Other	# 1			corrective date
Comment:	Observed distortion coming off rupture disc vent line/rupture disc leaking gas			
Corrective Action:	All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.			Date: 11/17/2023
Type: Gas Meter Run	# 1			
Comment:	Gas meter not calibrated annually/calibration card at gas meter shows meter has not been calibrated since 11/24/2021			
	Operator (Mustang) stated the meters on all of the Clough wells are owned and operated by TEP.			
Corrective Action:	Operator needs to install & calibrate their own meter or have TEP calibrate existing meter on location to comply with CECMC rules.			Date: 12/14/2023

Type: Other	# 2	
Comment:	PRV & rupture disc vent lines lack caps	
Corrective Action:	Vents on pressure safety devices will be designed to be clear and free of debris and water at all times.	Date: 11/21/2023
Type: Plunger Lift	# 1	
Comment:	Well on plunger lift	
Corrective Action:		Date:
Type: Deadman # & Marked	# 3	
Comment:	Marked	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210685	Type:	WELL	API Number:	045-06441	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Other	Fail					Erosion & transport of sediment
Compaction						Light compaction in some areas
Gravel						Sparse to none in areas
		Gravel				Sparse in sections
Berms						
		Compaction				
		Culverts				

Comment: [1. Erosion & transport of sediment](#)

Corrective Action: **Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.**

Date: 11/29/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment &amp; Stormwater for observed compliance issues.</a>	smelserw	11/14/2023
<a href="#">Duel lease - Shared pad with WF CLOUGH FEDERAL 14-24-6S-94W location # 311542</a>		

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902234	Inspection 708902233 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322340">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322340</a>
708902235	Inspection 708902233 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322341">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322341</a>