

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2023

Submitted Date:

11/09/2023

Document Number:

713600361**FIELD INSPECTION FORM**Loc ID 321069 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76859Name of Operator: SCHREIDER & COMPANY INCAddress: 8200 S QUEBEC ST SUITE A3-768City: CENTENNIAL State: CO Zip: 80112**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
SCHREIDER JR RUDY		schneiderco@outlook.com	
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
Wheeler, Steven		steven.wheeler@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
321069	LOCATION	AC			-	STATE-631S41W 17NWSE	RI

General Comment:

On 10/31/2023, Ryan Costa conducted a location inspection at the State 1-17 and Hume 1-20 facility.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	There is a pipe riser at the wellhead with no OOSLAT. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606. Remove all unused equipment. Remove pipe riser or LOTO.	Date:	10/31/2023
Type	WEEDS		
Comment:	There are weeds and dry vegetation debris around the equipment which is a fire hazard. The weeds around the location need to be controlled and debris removed. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	10/31/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	There is no netting at the open top tank located at the offsite facility Lat/Long:37.33139, -102.06825. Corrective action will remain out of compliance until completed.				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 10/31/2023

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	There is a vertical separator with no secondary containment. There is also no secondary containment at the offsite facility located at Lat/Long:37.33139, -102.06825. Corrective action will remain out of compliance until completed.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			
				Date: 10/31/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 321069 Type: LOCATION API Number: - Status: AC Insp. Status: RI**Flowline**

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment:	There is an offsite facility located Lat/Long:37.33139, -102.06825. It appears to be an active facility however there are no registered flowlines. There is a sign for Shrieder & Company and Dover Atwood at this facility with the name Hume 1-20.		
Corrective Action:	Submit an eForm 44 Flowline Report per Rule 1101.a. Contact ECMC Area Integrity Engineer.		Date: <u>10/31/2023</u>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403591139	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317235
713600365	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317225