


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 20 Pad
Location ID: 335068



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 15 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 20 Pad
Location ID: 335068



**Photo From inspection 707800037 conducted on
12/19/2022 Lack of stabilization/compaction**



Photo # 6840 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 20 Pad
Location ID: 335068



**Photo From inspection 707800037 conducted on
12/19/2022 Lack of stabilization/compaction**



Photo # 6841 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 20 Pad
Location ID: 335068



**Photo From inspection 707800037 conducted on
12/19/2022 Lack of stabilization/compaction**



Photo # 6842 Lack of stabilization/compaction

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 20 Pad
Location ID: 335068



Photo From inspection 707800037 conducted on 12/19/2022 Lack of stabilization/compaction



Photo # 6843 Lack of stabilization/compaction