

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/13/2023

Submitted Date:

11/14/2023

Document Number:

712700869

FIELD INSPECTION FORM

Loc ID 334036 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10755
Name of Operator: MORNINGSTAR OPERATING LLC
Address: 400 W 7TH ST
City: FORT WORTH State: TX Zip: 76102

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-----------------------------|------------------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Kittinger, Eric | | ekittinger@mspartners.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 268289 | WELL | PR | 08/20/2003 | CBM | 007-06198 | SCHUMACHER 32-6 13-1 | PR |
| 275732 | WELL | PR | 03/16/2005 | CBM | 007-06209 | SCHUMACHER 32-6 13-2 | PR |

General Comment:

[SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700382, submitted 7/10/2023. Corrective actions identified have not been completed.](#)

[Equipment inventory is listed on previous inspection, no change to location equipment.](#)

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access from CR 975. Unlocked gate. Gravel surface. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Metal signs posted on pumpjack fencing. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Content and volume label, NFPA placards on produced water tanks. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Warning signs at fenced enclosures. | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | 24 hour operator contact number and 911 local emergency number posted on well location signage. | | |
| Corrective Action: | | Date: | |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Observed piles of sucker rod on ground at both pumpjacks. Pieces/sections of process piping on ground around wellheads. Cable wheel stored on location. Pumpjack heads disconnected on the ground. Sections of fencing not connected. See photos #3-#8. This corrective action was identified in FIR Doc.#712700382, date is retained. | | |
| Corrective Action: | Return to service or remove as unused equipment per Rule 606. | | Date: 07/26/2023 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 268289 Type: WELL API Number: 007-06198 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 275732 Type: WELL API Number: 007-06209 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/26/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 18 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|-------------------------------|
| Ditches | Pass | Ditches | Pass | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | Gravel | Pass | | | |
| Berms | Pass | Culverts | Pass | Material Handling And Spill Prevention | Pass | Container within containment. |

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403594905 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6321330 |