

Location

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment: [good](#)

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type DEBRIS

Comment: [DEAD overgrown vegetation](#)

Corrective Action: [Comply with Rule 606](#)

Date: 11/21/2023

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: [safety guards](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: [Eletrical disconnect panel](#)

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: [electrical motor](#)

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202207 Type: WELL API Number: 001-07612 Status: PR Insp. Status: PR

Producing Well

Comment: PR, well appeared to be shut in at time of inspection
 Corrective Action: _____ Date: _____

Well Drilling

Rig: Rig Name: _____ Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____
 Comment: _____
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/10/2023 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 11-14-2023 at approximately 10:00, I, Inspector Michael Kester, conducted an on-site inspection. Location: Albert Sack D 1 Operator: KPK API#: 001-07612 County: Adams While there, I observed well site with pumping unit. During this inspection the following possible compliance issues were observed: Debris, comply with Rule 606, corrective action date 11-21-2023 Weather conditions: sunny & dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	11/14/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403595902	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322302
713300299	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6322300