

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2023

Submitted Date:

11/21/2023

Document Number:

713300310

FIELD INSPECTION FORMLoc ID 318409 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		randy.silver@state.co.us	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241248	WELL	PR	01/01/2022	OW	123-09036	MATHISEN UNIT A 2	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	concrete pumping unit support pad		
Corrective Action:	Comply with Rule 606	Date:	09/07/2023

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	pipe well head guard		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 241248 Type: WELL API Number: 123-09036 Status: PR Insp. Status: PR**Producing Well**Comment: PR, well appeared to be shut in at time of inspection

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 06/26/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

ECMC Inspection Report Summary
 On Tuesday 11-21-2023 at approximately 11:00, I, Inspector Michael Kester, conducted an on-site reinspection as per Doc # 713300038.
 Location: Mathisen Unit A 2
 Operator: KPK
 API# 123-09036
 County: Weld
 While there, I observed producing well site.
 At time of inspection it does not appear corrective actions from previous inspection have been address.
 Unused equipment, Rule 606, corrective action 9-7-2023, photo 1 & 2
 Weather conditions: sunny and dry
 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.
 This is a summary of inspection report.

This inspection does not nullify any orders or NOAV from the ECMC
 This is a continuing education inspection

kesterm

11/21/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300311	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6331740