

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2023

Submitted Date:

11/22/2023

Document Number:

696305430

**FIELD INSPECTION FORM**Loc ID 327437 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10391

Name of Operator: STONEHAM PRODUCTION LLC

Address: 5945 ZINNIA COURT

City: ARVADA State: CO Zip: 80004

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
William Penny		sierragas@aol.com	
,		rbarton@sterlingenergy.us	<a href="#">Sterling Energy</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246899	WELL	PR	06/01/2021	GW	123-14696	CRAIG 2	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained Soil at Wellhead; see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."		Date: 12/08/2023

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		40.718610,-103.663070	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 246899 Type: WELL API Number: 123-14696 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/13/2021Annual Brhd Completed? Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Annual Bradenhead Test is overdue12/08/2023Corrective Action: Complete Annual Bradenhead Test per Rule 419.c

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: NEOther: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: Type: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: SEOther: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date:

Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:			
Corrective	Date:		
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: Lat: Long:	
Reference Point: <u>SE</u>	Other:	Length: Width:	
<u>Lining:</u>			
Liner Type:	Liner Condition:		
Comment:			
Corrective	Date:		
<u>Fencing:</u>			
Fencing Type:	Fencing Condition:		
Comment:			
Corrective Action	Date:		
<u>Netting:</u>			
Netting Type:	Netting Condition:		
Comment:			
Corrective Action	Date:		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:			
Corrective Action	Date:		
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: Lat: Long:	
Reference Point: <u>SE</u>	Other:	Length: Width:	
<u>Lining:</u>			
Liner Type:	Liner Condition:		
Comment:			
Corrective	Date:		
<u>Fencing:</u>			
Fencing Type:	Fencing Condition:		
Comment:			
Corrective	Date:		
<u>Netting:</u>			
Netting Type:	Netting Condition:		
Comment:			
Corrective	Date:		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>	
Comment:			
Corrective	Date:		
Permit:	Facility ID	Permit Num	Expiration Date
	264215	1120638	

Inspector Name: PETRIE, ERICA

264216	1120639	
264217	1120640	
264217	1120640	
264214	1120637	

**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Stained Soil at Wellhead. Bradenhead Test Overdue</a>	petrie	11/22/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305431	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6332661">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6332661</a>