

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2023

Submitted Date:

11/27/2023

Document Number:

696305442**FIELD INSPECTION FORM**Loc ID 327106 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246371	WELL	SI	06/01/2018	GW	123-14168	NORTHRUP 1-14 (OWP)	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	2-Track Road to Location		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	TA Wellhead appears to have been disconnected from the Flowline		
Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 246371 Type: WELL API Number: 123-14168 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA - Wellhead appears to have been disconnected from the Flowline

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<u>Routine Field Inspection. OWP Well - All Production Equipment has been removed from Location. Gas Line remains. Wellhead appears to have been disconnected from Flowline. Flowline appears to have been removed.</u>	petrie	11/27/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305443	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6334975